

Product Specification Suberic Acid:

Chemical name :	Suberic Acid
Chemical name 2 :	1,8-Octandioic acid
Appearance :	white creamy powder
purity :	min 99 %
melting point :	140-144 °C
Moisture :	max 0,3 %
Einecs-No. :	208-010-9
CAS-No. :	505-48-6
Notes :	melting point : appx 144 °C
Synonym :	Octandisäure

Version: 09.07.2019

This data is only for your information purposes and does not imply a guarantee for a certain application.

